



MOTOROLA
Semiconductor Products Sector

Order Number: MCF5307UMAD/D
Rev. 0, 1/2001



Errata to ***MCF5307 ColdFire® Microprocessor User's Manual***

These errata describes corrections to the *MCF5307 ColdFire Microprocessor User's Manual*. For convenience, the section number and page number of the errata item in the user's manual are provided. The MCF5307 device referred to in this document is the MCF5307FTxxB. Please check the WWW at <http://www.motorola.com/ColdFire> for the latest updates.

This document contains information on a new product under development by Motorola. Motorola reserves the right to change or discontinue this product without

© Motorola, Inc., 2001. All rights reserved.



2.6, 2-40

Add the following text:

Note that if the upper 16 bits of a longword aligned fetch location contain an unknown (illegal) opcode while the lower 16 bits contain a Bxx.B opcode (where Bxx = BRA, BSR, Bcc), an incorrect re-direction of the prefetch stream to an improper target location will occur. An example of this is seen in the following code:

```
mov.l (4,%pc,%d0.l*4),%a0
jmp   (%a0)
label:
long  label1
long  label2
```

In this case, the code would disassemble to the following:

```
X-6: 207b 0c04 #mov.l
X-2: 4ed0      #jmp
X+0: wxyz 6040 #pointer to label1 (example)
X+4: .....   #pointer to label2
```

In this example, after the JMP instruction, the label pointer disassembles to what looks like an unknown opcode (wxyz = any unknown opcode) followed by a 16-bit opcode that looks like a Bxx.B opcode, but actually isn't. In this case, the branch acceleration logic calculates the target address and begins prefetching at X + 0x44. This can be particularly problematic if the address that the acceleration logic jumps to is at an offset range that doesn't exist, resulting in an illegal access. More specifically, if the 8-bit displacement that is decoded in the look-alike Bxx.b instruction branches to an offset (-128 byte to +128 byte) that no chip-select is programmed to or where no memory exists, then the bus cycle hangs. However, if the offset is in a chip-select or memory range, although the branch is to an improper address location, the error eventually recovers when the JMP instruction (at X-2) is executed in the operand execution pipeline.

To avoid this scenario, put a 128-byte space at the beginning and end of any code sections that might be affected by this sequence, so calculation of the improper target address does not impact system operation.

In addition, the assembly language for label or case statements as defined above can be modified to guarantee the problem does not occur. The use of the illegal opcode prior to the table of addresses prevents improper code re-direction. Note that the ColdFire ISA illegal opcode is different from the unknown, illegal opcodes referenced above. An example of the illegal opcode in a program is as follows:

```
mov.l (6,%pc,%d0.l*4),%a0 # offset changed to "6"
jmp   (%a0)
illegal                                # added instruction as workaround
label:
long  label1
long  label2
```

Section #/Page #**Changes**

3.1.2, 3-3

Add the following text:

If 16-bit MAC instruction operands are being used from different halves of different CPU registers, and if the V bit is being checked or if the MAC unit is operating in saturation mode, code modifications are required to ensure that the overflow logic works properly. For instance, `mac.wRx:u,Ry:l` should be replaced with the following equivalent sequence:

```
swap      Rx
mac.w     Rx:l,Ry:l
swap      Rx
```

`mac.wRx:l,Ry:u` should be replaced with the following sequence:

```
swap      Rx
mac.w     Rx:u,Ry:u
swap      Rx
```

Of course, the second swap instruction in each case should be removed if the MAC instruction specifies a memory operand that is to be loaded into the Rx register.

Similar sequences should be substituted for MSAC.W instructions.

The case for 16-bit operands from different halves of the same CPU register (`y == x`) is slightly more complicated. The instruction:

```
mac.w     Rx:u,Rx:l
```

should be replaced with:

```
cmp.l     x,&0x80008000
bne.b     label1
mac.w     Rx:l,Rx:l
bra.b     label2
```

```
label1:
mac.w     Rx:u,Rx:l
```

```
label2:
```

Similar sequences should be used for MSAC.W instructions.

5.4.4, 5-11

In the description of the EMU bit, replace the bit description with the following text:

Do not set bit 13 of the debug module's Configuration/Status Register. The quickest entry into emulator mode after reset is created with the following sequence:

1. While in the BDM initiation sequence, program a debug breakpoint trigger event by an operand reference to address 0x0 or 0x4. As part of this sequence, the debug interrupt vector must also be initialized to the same address as the initial PC defined at address 4.

Section #/Page #	Changes
	<p>2. When the BDM GO command is received by the processor, the reset exception processing fetches the longwords at addresses 0 and 4 in normal mode and then a debug interrupt is immediately generated before the first instruction is executed.</p> <p>3. Execution continues in emulator mode.</p>
5.4.7, 5-14	<p>Replace the last two sentences in the first paragraph with the following:</p> <p>Breakpoint logic can be configured as a single one-level trigger or a combination of one-level triggers. TDR[15:0] define the first-level trigger.</p>
5.4.7, 5-15	<p>Add the following text:</p> <p>NOTE: The second-level trigger does not work properly on the MCF5307. TDR[29:15] are effectively reserved bits.</p>
5.4.7, 5-16	<p>In the description for the DI bit, add the following text:</p> <p>Do not set DI for word or longword breakpoints.</p>
5.6.1, 5-42	<p>Add the following text:</p> <p>If debug interrupts are enabled, disable the capturing of operand writes because the stream of PST[3:0] = 0xD values may not be contiguous. Alternatively, ignore PST[3:0] = 0x0 values occurring during a debug interrupt. Let the debug interrupt exception processing be defined from the initial PST[3:0] = 0xD until PST[3:0] = 0x5.</p>
6.2.10.1, 6-11	<p>Table 6-6, PARK bit description, add the following text:</p> <p>NOTE: If round-robin mode (00) is selected, ensure that DCR[BWC] is set higher than the value in the BCR. If park-on-internal-DMA (10) or park-on-ColdFire-core (01) is selected, select DCR[BWC] = 000.</p>
9.2.3, 9-6	<p>Add the following text:</p> <p>NOTE: For interrupts sources with levels 1–6, write a higher level interrupt mask to the status register before setting the IMR. After the IMR is set, return the interrupt mask in the status register to its previous value. Do not mask a level-7 interrupt in the IMR. If these precautions are not followed, a spurious interrupt may occur.</p>
11.4.2, 11-18	<p>Add the following text:</p> <p>NOTE: Glitches may occur on the address lines unless EDGESEL is tied high or BCLKO is qualified with the assertion of $\overline{\text{SRAS}}$ or $\overline{\text{SCAS}}$ before connecting to the EDGESEL input. These glitches do not affect DRAM controller operation and are within the undershoot limits specified by Figure 1 of this document.</p>
12.4.4, 12-9	<p>Table 12-3, BWC bit description, add the following text:</p> <p>NOTE: Do not select the 000 encoding when MPARK[PARK]=00; the BWC encoding must be set higher than the value in the BCR in this mode. If MPARK[PARK]=10 or 01, BWC should equal 000.</p>

Section #/Page #	Changes
12.5.2.1, 12-13	Add the following text: NOTE: Use the CPU to write to the UART transmitter buffer. The DMA module is not able to properly transfer information from memory to the UART.
12.5.2.2, 12-13	Add the following text: Do not use single address access mode in cycle-steal mode; errant accesses may occur.
18.9, 18-23	Add the following text: NOTE: Either do not allow external master access to SDRAM using the MCF5307 DRAM controller or provide external termination for SDRAM bus cycles by an external master. The MCF5307 does not provide correct termination for external bus masters using the on-chip SDRAM controller.
20.1 20-2	Add the following diagram and text: Figure 1 shows the allowable undershoot voltage on the MCF5307. Note that 1.2-V undershoot is only allowable if it is present 1% or less of the total processor operating time.




Figure 1. Undershoot Voltage

20.3 20-4	Make the following changes in Table 20-6: Change the Min specification for B14 to 2.0 nS for 66 MHz. Change the Min specification for B16 to 2.0 nS for 66 MHz.
-----------	---

Section #/Page #


Changes

DigitalDNA is a trademark of Motorola, Inc.

The ColdFire name, the ColdFire logotype, and ColdFire 5307 are trademarks of International Business Machines Corporation used by Motorola under license from International Business Machines Corporation.

Information in this document is provided solely to enable system and software implementers to use PowerPC microprocessors. There are no express or implied copyright licenses granted hereunder to design or fabricate PowerPC integrated circuits or integrated circuits based on the information in this document.

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters can and do vary in different applications. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part.

Motorola and  are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

Motorola Literature Distribution Centers:

USA/EUROPE: Motorola Literature Distribution; P.O. Box 5405; Denver, Colorado 80217; Tel.: 1-800-441-2447 or 1-303-675-2140;
World Wide Web Address: <http://ltdc.nmd.com/>

JAPAN: Nippon Motorola Ltd SPD, Strategic Planning Office 4-32-1, Nishi-Gotanda Shinagawa-ku, Tokyo 141, Japan Tel.: 81-3-5487-8488

ASIA/PACIFIC: Motorola Semiconductors H.K. Ltd Silicon Harbour Centre 2, Dai King Street Tai Po Industrial Estate Tai Po, New Territories, Hong Kong

World Wide Web Address: <http://sps.motorola.com/mfax>

INTERNET: <http://motorola.com/sps>

Technical Information: Motorola Inc. SPS Customer Support Center 1-800-521-6274; electronic mail address: crc@wmkmail.sps.mot.com.

Document Comments: FAX (512) 933-2625, Attn: RISC Applications Engineering.

World Wide Web Addresses: <http://www.motorola.com/PowerPC>

<http://www.motorola.com/netcomm>

<http://www.motorola.com/Coldfire>



MOTOROLA

MCF5307UMAD/D